

Final Reclamation Inspection

July 15 2023

Operator: PDC ENERGY INC - 69175

Location ID: 305383

Inspection Document #: 701900988

NESW Section 28 T7N R65W

Corey McDonough
Reclamation Contractor, COGCC



CO L O R A D O

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hazen 23-28
Location ID: 305383



Photo 1. 2023 aerial imagery of the well pad, access road and tank battery (north is up).

Inspection Photos
Location Name: Hazen 23-28
Location ID: 305383




Photo 2. Overview photo of the tank battery, access road and well pad, taken from the eastern edge facing west using a drone. Note: well pad, access road and tank battery appear consistent with adjacent crop reference area. Slight stunting crop appears outside of the tank battery disturbance and does not appear to be related to oil and gas operations.

Inspection Photos
Location Name: Hazen 23-28
Location ID: 305383



Photo 3. Overview photo of the well pad and tank battery crop field taken at ground level from the eastern edge of the tank battery facing west.