

# Final Reclamation Inspection

July 15 2023

Operator: PDC ENERGY INC - 69175

Location ID: 327239

Inspection Document #: 701901000

SWSW Section 21 T4N R66W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Byron 13-21  
Location ID: 327239



**Photo 1.** 2023 aerial imagery of the well pad, access road and tank battery (north is up).



Inspection Photos  
Location Name: Byron 13-21  
Location ID:327239



**Photo 2.** Overview photo of the well pad and access road. Note: well pad appears consistent with adjacent crop reference area. Riser to the south of the well disturbance was built 3 years after the well was plugged and abandoned and is not associated with PDC oil and gas operations.



Inspection Photos  
Location Name: Byron 13-21  
Location ID:327239



07/15/2023 16:26

**Photo 3.** Overview photo of the tank battery taken at ground level.  
Note: tank battery falls within a parking area next to a residential home.