

Final Reclamation Inspection

July 16th 2023

Operator: PDC ENERGY INC - 69175

Location ID: 407785

Inspection Document #: 701901004

SENE Section 5 T5N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Mininger Pfeif 1
Location ID: 407785



Photo 1. 2023 aerial imagery of the well pad, access road and tank battery (north is up).

Inspection Photos
Location Name: Miner Pfeif 1
Location ID:407785




Photo 2. Overview photo of the well pad, access road and tank battery taken with a drone from the southern edge facing north. Note: well pad, access road and tank battery all appear consistent with the adjacent crop reference area. Access point remains as the access point for the southern side of the field.

Inspection Photos
Location Name: Mininger Pfeif 1
Location ID:407785



Photo 3. Ground photo of the well pad access field taken from the southern edge of the tank battery.