

# Final Reclamation Inspection

July 17th 2023

Operator: PDC ENERGY INC - 69175

Location ID: 310588

Inspection Document #: 701901015

NESE Section 17 T5N R67W

Corey McDonough  
Reclamation Contractor, COGCC




**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Hankins 17-DU  
Location ID:310588



**Photo 1.** 2023 aerial imagery of the well pad and tank battery (north is up).

Inspection Photos  
Location Name: Hankins 17-DU  
Location ID:331144



**Photo 2.** Overview photo of the tank battery. Photo shows that the operator has failed to perform final reclamation activities. Gravel, access points and culverts remain on location.

Inspection Photos  
Location Name: Hankins 17-DU  
Location ID:331144



**Photo 3.** Overview photo of the well pad taken at ground level from the southern edge facing north.

Inspection Photos  
Location Name: Hankins 17-DU  
Location ID:331144



**Photo 4.** Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos  
Location Name: Hankins 17-DU  
Location ID:331144



**Photo 5.** Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: photo shows that the well pad appears consistent with adjacent reference area (see photo 6).

Inspection Photos  
Location Name: Hankins 17-DU  
Location ID:331144



**Photo 6.** Reference area.