

# Final Reclamation Inspection

July 17th 2023

Operator: PDC ENERGY INC - 69175

Location ID: 331416

Inspection Document #: 701901018

NENE Section 21 T4N R67W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources


Inspection Photos  
Location Name: Fickel 41-21  
Location ID: 331416



**Photo 1.** 2023 aerial imagery of the well pad, access road and tank battery (north is up).



Inspection Photos  
Location Name: Fickel 41-21  
Location ID:331144



**Photo 2.** Overview photo of the access road and well pad taken from the northern edge facing southern using a drone. Photo shows that the well pad and access road appear consistent with adjacent reference area.



Inspection Photos  
Location Name: Fickel 41-21  
Location ID:331144



**Photo 3.** Overview photo of the tank battery taken at ground level from the northern edge facing southwest.



Inspection Photos  
Location Name: Fickel 41-21  
Location ID:331144



**Photo 4.** Cardinal photos taken from the middle of the tank battery.  
Left photo facing north, right photo facing east.



Inspection Photos  
Location Name: Fickel 41-21  
Location ID:331144



**Photo 5.** Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Photo shows that the operator failed to remove risers at the location.



Inspection Photos  
Location Name: Fickel 41-21  
Location ID:331144



**Photo 6.** Photos of the tank battery access point and culvert. Photo shows that the operator failed to reclaim the access point and remove culverts.





**Photo 7.** Stormwater erosion observed along the northern edge of the tank battery.