

Final Reclamation Inspection

July 17th 2023

Operator: PDC ENERGY INC - 69175

Location ID: 323641

Inspection Document #: 701901020

NWNE Section 28 T4N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McCarty 28-6
Location ID: 323641




Photo 1. 2023 aerial imagery of the well pad, access road and tank battery (north is up).

Inspection Photos
Location Name: McCarty 28-6
Location ID:331144




Photo 2. Overview photo of the well access road and well pad taken from the northern edge facing south. Photo shows that that the access road and well pad appear consistent with the adjacent crop reference area.



Inspection Photos
Location Name: McCarty 28-6
Location ID:331144




Photo 3. Overview photo of the tank battery taken from the northern edge facing south using a drone. Photo shows that the tank battery does not appear consistent with adjacent crop reference area.

Inspection Photos
Location Name: McCarty 28-6
Location ID:331144



Photo 4. Overview photo of the tank battery taken at ground level from the northern edge facing south.