

Final Reclamation Inspection

July 17th 2023

Operator: PDC ENERGY INC - 69175

Location ID: 323388

Inspection Document #: 701901021

SENW Section 28 T4N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McCarty 28-4
Location ID: 323388



Photo 1. 2023 aerial imagery of the well pad and access road (north is up).

Inspection Photos
Location Name: McCarty 28-4
Location ID:331144



Photo 2. Overview photo of the well pad crop field. Photo shows that the field has been harvested. Location will remain in-process until the site can be re-inspected during the next growing season to make an accurate assessment of the vegetation.