

Final Reclamation Inspection

July 17th 2023

Operator: PDC ENERGY INC - 69175

Location ID: 319545

Inspection Document #: 701901022

SWSE Section 1 T3N R68W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Seewald 1-1
Location ID: 323388




Photo 1. 2023 aerial imagery of the access road, tank battery and well pad (north is up). Note: well pad and tank battery share a disturbance area.

Inspection Photos
Location Name: Seewald 1-1
Location ID:319545



Photo 2. Overview photo of the access road, well pad and tank battery taken from the southern edge facing north using a drone.

Inspection Photos
Location Name: Seewald 1-1
Location ID:319545



Photo 3. Overview photo of the tank battery/well pad taken at ground level from the southern edge facing northeast. Photo shows that the area has stunted alfalfa growth and is dominated by kochia.