

## Inspection Photos

Location Name: Burckle A Pad

Location ID: #335540

Inspection Date: July 27, 2023



Photo #1 – Pad sign.



Photo #2 – Two locations are present in NE corner of pad.



**Inspection Photos**  
**Location Name: Burckle A Pad**  
**Location ID: #335540**  
**Inspection Date: July 27, 2023**



**Photo #3 – Localized accumulation of vegetable debris at tank heater. Note red circle documents presence of a rag at the manhole cover, by the heater.**



**Photo #4 – Marked, unused flowline riser located on south end of tank battery.**



**Inspection Photos**  
**Location Name: Burckle A Pad**  
**Location ID: #335540**  
**Inspection Date: July 27, 2023**



**Photo #5 – View of northern tank battery.**



**Photo #6 – Marked, unused flowline riser located on east end of northern tank battery.**



**Inspection Photos**  
**Location Name: Burckle A Pad**  
**Location ID: #335540**  
**Inspection Date: July 27, 2023**



**Photo #7 – Horizontal heated separators located on south end of tank battery.**



**Photo #8 – Multiple marked, unused flowline risers located west of separator battery.**



**Inspection Photos**  
**Location Name: Burckle A Pad**  
**Location ID: #335540**  
**Inspection Date: July 27, 2023**



**Photo #9 – Additional marked, unused flowline risers located at separator for Burckle A8 well (circled in red).**



**Photo #10 – Overview of wellhead area.**