

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ISLAND PARK B Pad

Location #: 336025



Jul 31, 2023 at 9:44:37 AM  
CO

Photo # 4178 From entrance to location



Jul 31, 2023 at 9:45:56 AM  
CO

Photo # 4179 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ISLAND PARK B Pad

Location #: 336025




Photo # 4181 Location



Photo # 4182 Location





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ISLAND PARK B Pad

Location #: 336025



Photo # 4185 Location



Photo # 4186 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ISLAND PARK B Pad

Location #: 336025



**Photo # 542 From inspection 708900771 conducted on 06/15/2023 Unused equipment/ECD is disconnected**



**Photo # 4191 Unused equipment/ECD is disconnected**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ISLAND PARK B Pad

Location #: 336025



**Photo # 543 From inspection 708900771 conducted on 06/15/2023 Unused equipment/ECD is disconnected**



**Photo # 4195 Unused equipment/ECD is disconnected**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ISLAND PARK B Pad

Location #: 336025



Photo # 4196 Unused equipment/ECD is disconnected



Photo # 4198 Unused equipment/ECD is disconnected





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ISLAND PARK B Pad

Location #: 336025



Photo # 4188 ECD line disconnected at tank battery



Photo # 4189 Debris