

Inspection Photos
Location Name: Coulter 9-12
Location ID: 305770



Photo 1 Weeds growing tall around location fencing.

Photo 2 Weeds growing tall around location fencing.

Inspection Photos
Location Name: Coulter 9-12
Location ID: 305770



Photo 3 WH sign.



Photo 4 WH.