

Inspection Photos
Location Name: Coulter 15-12
Location ID: 309938



Photo 1 Location



Photo 2 Weeds growing tall around location fencing.



Inspection Photos
Location Name: Coulter 15-12
Location ID: 309938



Photo 3 Weeds growing around WH sign.



Photo 4 Weeds growing around the WH.

Inspection Photos
Location Name: Coulter 15-12
Location ID: 309938



Photo 5 Weeds growing around WH location.