

TEP
GV 4-33
Location ID:
335285



Tank battery



Separators and lack of access to calibration cards

TEP
GV 4-33
Location ID:
335285



Open cellar with trapped and dead wildlife



Open cellar with trapped and dead wildlife



TEP
GV 4-33
Location ID:
335285



Open cellar with trapped and dead wildlife



Open cellars

TEP
GV 4-33
Location ID:
335285



Open cellars



Open cellars

TEP
GV 4-33
Location ID:
335285



Cut slope not stabilized and erosion present with sediment encroaching on production equipment



Cut slope not stabilized and erosion present with sediment encroaching on production equipment

TEP
GV 4-33
Location ID:
335285



Cut slope not stabilized and erosion present with sediment encroaching on production equipment



Cut slope not stabilized and erosion present with sediment encroaching on production equipment