


335411



## Well heads



### Tank battery open line on top of tank



TEP  
PA 42-33  
Location ID:  
335411



**Separators and lack of access to calibration cards**



**Areas of cut slope need stabilization**



TEP  
PA 42-33  
Location ID:  
335411



**Debris**



**Sediment trap and BMP's need maintained**



TEP  
PA 42-33  
Location ID:  
335411



**Sediment trap needs maintained**