

# Construction & Stormwater Inspection

July 28, 2023

Operator: Crestone Peak Resources, #10633

Location ID: 482249

Inspection Document # **709400371**

Weld, CO

NENE, 34 3N66W 6

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name:Divoe 34H-A366 Battery

Location ID:482249



Photo 1. Photo of location sign.



Photo 2. Photo of tank battery.

Inspection Photos

Location Name:Divoe 34H-A366 Battery

Location ID:482249



**Photo 3.** Photo of weeds on stie.



**Photo 4.** See Photo 3 comments