

Construction & Stormwater Inspection

July 20, 2023

Operator: GMT Exploration Co, #10243

Location ID: 484179

Inspection Document # 709400375

Elbert, CO

4 6S64W

Reed Wold
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Ragged 6-64 4

Location ID:484179



Photo 1. Photo of Topsoil stockpile.



Photo 2. Photo of ditch at the perimeter of site.

Inspection Photos

Location Name: Ragged 6-64 4

Location ID:484179



Photo 3. Photo of Northwest sediment trap.



Photo 4. Photo of cut slope perimeter ditch.

Inspection Photos

Location Name: Ragged 6-64 4

Location ID:484179



Jul 20, 2023 at 11:38:11 AM
Elizabeth CO 80107
United States

Photo 5. Photo of Southeast sediment trap and perimeter ditch



Jul 20, 2023 at 11:38:25 AM
Elizabeth CO 80107
United States

Photo 6. Photo of fill slope and perimeter ditch

Inspection Photos
Location Name: Ragged 6-64 4
Location ID:484179



Photo 7. Photo of stormwater retention pond at entrance of pad.



Photo 8. Photo of inlet of culvert at entrance of pad

Inspection Photos

Location Name: Ragged 6-64 4

Location ID:484179



Photo 9. Photo of access road to pad



Photo 10. Photo of outlet of culvert at entrance of pad.