

# Construction & Stormwater Inspection

July 20, 2023

Operator: GMT Exploration Co, #10243

Location ID: 484163

Inspection Document # 709400377

Elbert, CO

S2NW, 19 6S64W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: Cinnamon 6-64 19-7

Location ID:4884163



**Photo 1.** Photo of access road from county road.



**Photo 2.** Photo of wind rowed soil on access road, No stormwater BMPs present.

Inspection Photos

Location Name: Cinnamon 6-64 19-7

Location ID:4884163



**Photo 3.** Photo of scraping topsoil.



**Photo 4.** Photo of topsoil stockpile.

Inspection Photos

Location Name: Cinnamon 6-64 19-7

Location ID:4884163



**Photo 5.** Photo of Southeast perimeter ditch



**Photo 6.** Photo of Southeast sediment trap and perimeter ditch

Inspection Photos

Location Name: Cinnamon 6-64 19-7

Location ID:4884163



**Photo 7.** Photo of perimeter ditch on fill slope side.



**Photo 8.** See Photo 7

Inspection Photos

Location Name: Cinnamon 6-64 19-7

Location ID:4884163



**Photo 9.** Photo of perimeter ditch on South west corner of site.



**Photo 10.** Photo of perimeter ditch leading to access road.