

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: ANTELOPE 42-19 Pad

Loc ID: 413543

Inspection: 696305130



Exhibit A

CA: Tumbleweed Debris at P-19 Wellhead; see photos. Comply with Rule 606.

CA Resolution: Operator has reported that the identified tumbleweeds have been cleared from location to comply with Rule 606.