

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Antelope 11-20

Loc ID: 424418

Inspection: 696305133



Exhibit A

CA: Unmarked Risers at Wellheads; see photos. Comply with Rule 606.

CA Resolution: Operator has appropriately installed markers on Risers at Wellheads to comply with Rule 606.





Exhibit C

CA: Tumbleweed Debris at Wellheads; see photos. Comply with Rule 606.

CA Resolution: Operator has reported that the identified tumbleweeds have been cleared from location to comply with Rule 606.