

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Jul 31, 2023 at 9:12:25 AM
CO



Jul 31, 2023 at 9:13:03 AM
CO

Photo # 4139 From entrance to location

Photo # 4140 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 4143 Location



Photo # 4144 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 4145 Location



Photo # 4146 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 501 From inspection 708900775 conducted on 06/15/2023 Unused equipment



Photo # 4160 Unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 4173 Unmarked deadman



Photo # 4174 Same unmarked deadman from a different view