

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Antelope J-19 PAD

Loc ID: 430139

Inspection: 696305114



Exhibit A

CA: Tanks 2205080 and 220509 NFPA Labels have faded no longer visible; see photos. Install sign to comply with Rule 605.h.

CA Resolution: Operator has provided photo evidence and noted that NFPA Labels have been installed to comply with Rule 605.h.



Exhibit A



Exhibit B

CA: Tumbleweed Debris at Separators. Comply with Rule 606.

CA Resolution: Operator has reported that the identified tumbleweeds have been cleared from location to comply with Rule 606.



Exhibit A

CA: Out of date Locate Flags on location in varies spots; see photos. Comply with Rule 606.

CA Resolution: Field has reported that most of the locate flags have been removed; however, a few will need to remain on the East side of the tanks while there is active work being done to the water line. Field will be sure to remove these flags when maintenance has been completed to comply with Rule 606.



Exhibit A

CA: Line Heater missing Bird Protector; see photos. Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.

CA Resolution: Operator has provided photo evidence and noted wildlife protective netting has been appropriately installed to comply with Rule 902.b.