

**Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC**

**Location Name: Antelope I-17**

**Loc ID: 420880**

**Inspection: 696305135**



Exhibit A

**CA:** Middle Tank - NFPA Label; see photos. Install sign to comply with Rule 605.h.

**CA Resolution:** Operator has provided photo evidence and noted that NFPA Labels have been installed to comply with Rule 605.h.



Exhibit A



Exhibit B

**CA:** Tumbleweed Debris at Separators. Comply with Rule 606.

**CA Resolution:** Operator has reported that the identified tumbleweeds have been cleared from location to comply with Rule 606.