

Inspection Photos

7/31/2023

Operator: CAERUS PICEANCE LLC #10456

Location Number: 334927

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334927



Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview of the location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 334927



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334927



Photo 3: Photos example showing that though vegetation on the Location is predominantly undesirable plant species, desirable plant germination and establishment is evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334927



Photo 4: Photos example showing that though vegetation on the Location is predominantly undesirable plant species, desirable plant germination and establishment is evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources