

Inspection Photos

API: 071-09050

Operator: WAPITI OPERATING LLC

Inspection Date: 7/31/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09050 | Date: 7/31/2023

Inspection Photos



Photo 1. Facing northeast toward the location.



Inspection Photos



Photo 2. Facing northwest at the location. There are still noxious weeds (Canada thistle) at the southeast portion of the location that needs to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09050 | Date: 7/31/2023

Inspection Photos



Photo 3. Facing northwest toward the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09050 | Date: 7/31/2023