

# Inspection Photos

API: 071-09013

Operator: WAPITI OPERATING LLC

Inspection Date: 7/31/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09013 | Date: 7/31/2023

## Inspection Photos



**Photo 1.** Facing northeast along the access road at Latitude: 37.00784 Longitude: -104.858674. This electric utility is leaking oil that needs to be repaired and cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09013 | Date: 7/31/2023



## Inspection Photos



**Photo 2.** There is oil stained soils at the electric utility that needs to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09013 | Date: 7/31/2023



## Inspection Photos



**Photo 3.** Facing northeast along the access road. There is erosion along the roadside which needs BMP's to control erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09013 | Date: 7/31/2023

## Inspection Photos



**Photo 4.** Facing northeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09013 | Date: 7/31/2023