

Inspection Photos
Location Name: Dreyer #1
Location ID: 317620



Photo 1 Access road completely covered in vegetation.



Photo 2 Well head

Inspection Photos
Location Name: Dreyer #1
Location ID: 317620



Photo 3 TNK BTRY



Photo 4 Production equipment. Meter run could not access due to hornets nest.

Inspection Photos
Location Name: Dreyer #1
Location ID: 317620



Photo 5 access road and location overgrown weeds and Noxious weeds on site.



Photo 6 weeds and noxious weeds on permitted area of location.