

Inspection Photos

7/31/2023

Operator: CAERUS PICEANCE LLC #10456

Location Number: 323927

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 323927



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview of the location from east, southeast southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 323927



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 323927



Photo 3: Fence in disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 323927



Photo 4: Central areas of the Location; areas may require additional reclamation.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 323927



Photo 5: Undesirable Plant Species (Field Bindweed) establishing on the Location.