

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: ANTELOPE 42-19 RTB

Loc ID: 418214

Inspection: 696305128



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F

CA: Tumbleweed Debris at Separators and Tanks; see photos. Comply with Rule 606.

CA Resolution: Operator has reported that the identified tumbleweeds have been cleared from location to comply with Rule 606.



Exhibit A



Exhibit B

CA: Unmarked Risers at Separators buried by Tumbleweed Debris; see photos. Comply with Rule 606.

CA Resolution: Risers at Separators have been appropriately marked to comply with Rule 606.



Exhibit A

CA: Northeast 300 BBL Tank - NFPA Label; see photos. Install sign to comply with Rule 605.h.

CA Resolution: Operator has provided photo evidence and noted that NFPA Labels have been installed to comply with Rule 605.h.