

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Nichols/24-07

Location ID: 450760

Date: 8/1/2023



NW Corner of Location – Photo #05317



SW Corner of Location – Photo #05318

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Nichols/24-07

Location ID: 450760

Date: 8/1/2023



SE Corner of Location – Photo #05319



NE Corner of Location – Photo #05320

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Nichols/24-07

Location ID: 450760

Date: 8/1/2023



Wellheads – Photo #05322



Separators – Photo #05325

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Nichols/24-07

Location ID: 450760

Date: 8/1/2023



Tank Battery – Photo #05330



Location Lacks Stabilization – Photo #05323

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Nichols/24-07

Location ID: 450760

Date: 8/1/2023



Location Lacks Stabilization – Photo #05324



Location Lacks Stabilization – Photo #05328

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Nichols/24-07

Location ID: 450760

Date: 8/1/2023



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #05329