

Interim and Stormwater Inspection

July 5, 2023

Operator: Kerr McGee Oil & Gas # 47120

Location ID: 479835

Inspection Document #:709400382

Weld, County

SWNE, Section 35 3N66W

Reed Wold

Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Brown/Cannon Tank Battery

Location ID:479835



Photo 1. Photo taken of Location sign.



Photo 2. Photo taken of tank battery

Inspection Photos
Location Name: Brown/Cannon Tank Battery
Location ID:479835



Photo 3. Photo of weeds in containment



Photo 4. Photo of weed debris in containment.



Inspection Photos

Location Name: Brown/Cannon Tank Battery

Location ID:479835



Photo 5. Photo taken of weeds

Photo 6. See photo 5 comments.

