

Construction & Stormwater Inspection

July 20, 2023

Operator: Crestone Peak, #10633

Location ID: 430283

Inspection Document # 709400389

Weld, CO

NWNE, 2 2N66W

Reed Wold
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Ione NE 2H Battery

Location ID:430283



Photo 1. Photo of location sign on site.



Photo 2. Photo of Tank battery

Inspection Photos

Location Name: lone NE 2H Battery

Location ID:430283



Photo 3. Photo of Stormwater erosion on site.



Photo 4. Photo of stormwater erosion bypassing rock rundown.

Inspection Photos

Location Name: lone NE 2H Battery

Location ID:430283



Photo 5. Photo of Weeds piled against fence



Photo 6. Photo of stormwater erosion on site.

Inspection Photos

Location Name: lone NE 2H Battery

Location ID:430283



Photo 7. Photo of Weeds accumulated on site



Photo 8. Photo of stormwater erosion on site.

Inspection Photos

Location Name: lone NE 2H Battery

Location ID:430283



Photo 9. Photo of rock run down filled with sediment.



Photo 10. Photo of buried culvert at pad entrance of pad