

Construction & Stormwater Inspection

July 12, 2023

Operator: Crestone Peak, # 10633

Location ID: 323186

Inspection Document # 709400411

Weld, CO

NWNW, 30 2N64W

Reed Wold
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Gurtler Battery
Location ID: 323186



Photo 1. Photo of location sign on site.



Photo 2. Photo of tank battery.

Inspection Photos

Location Name: Gurtler Battery

Location ID: 323186



Jul 13, 2023 at 10:11:42 AM
Hudson CO 80642
United States

Photo 3. Photo of equipment on ste.