

# Inspection Photos

7/31/2023

Operator: CAERUS PICEANCE LLC #10456

Location Number: 334603

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334603



**Photo 1:** Photos 1-2 taken from the north end of the Location. Photos provide an overview of the location from east, southeast southwest to west.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334603



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 334603



Photo 3: Tank battery facility.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

# Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Jul 31, 2023 Panorama Plan



**Photo 4:** sUAS of the interim areas on the northeast end of the Location. Arrows within image show apparent berm remaining, potentially impacted soils, and gravel within a containment berm where equipment was previously Located.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334603



**Photo 5:** Gravel within a containment berm.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334603



**Photo 6: Remaining pipe debris**



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334603



**Photo 7:** Apparent berm remaining on the southern perimeter of the disturbance.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources