

**Inspection Photos**  
**Location Name: Marvin E. Schutt Unit 1**  
**Location ID: 318480**



**Photo 1 Location**

**Photo 2 WH/sign.**

**Inspection Photos**  
**Location Name: Marvin E. Schutt Unit 1**  
**Location ID: 318480**



**Photo 3 Undesirable Plant Species (vegetation) growing around the WH.**



**Photo 4 Undesirable Plant Species (vegetation) growing around the Pump Jack**

**Inspection Photos**  
**Location Name: Marvin E. Schutt Unit 1**  
**Location ID: 318480**



Colorado Energy & Carbon Management Commission  
40.1108, -104.88856, 4981.1ft  
08/02/2023 11:43:15

**Photo 5 Undesirable Plant Species (vegetation) growing around the PJ Base.**



Colorado Energy & Carbon Management Commission  
40.11078, -104.88858, 4980.9ft  
08/02/2023 11:43:25

**Photo 4 Undesirable Plant Species (vegetation) growing around the Pump Jack Base.**

**Inspection Photos**  
**Location Name: Marvin E. Schutt Unit 1**  
**Location ID: 318480**



**Photo 5 Undesirable Plant Species (vegetation) growing around the Ancillary equip.**



**Photo 4 Undesirable Plant Species (vegetation) growing around the Ancillary equip.**