

# Interim & Stormwater Inspection

July 26, 2023

Operator: Crestone Peak, # 10633

Location ID: 444192

Inspection Document # 709400438

Adams, CO

NWSW, 27 3S65W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Florida 3-65  
Location ID: 454192



Photo 1. Photo of location sign on site.



Photo 2. Photo of tank battery.

Inspection Photos  
Location Name: Florida 3-65  
Location ID: 454192



**Photo 3.** PHoto of stain outside of containment.



**Photo 4.** Stormwater erosion above culvert from access road.