

Interim & Stormwater Inspection

July 26, 2023

Operator: Crestone Peak, # 10633

Location ID: 449176

Inspection Document # 709400440

Adams, CO

NESE, 28 3S65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: King 3-65
Location ID: 449176



Photo 1. Photo of location sign on site.



Photo 2. Photo of tank battery.

Inspection Photos
Location Name: King 3-65
Location ID: 449176



Photo 3. Photo of trash on site.



Photo 4. Photo of weeds on site.