

# Interim & Stormwater Inspection

July 26, 2023

Operator: Crestone Peak, # 10633

Location ID: 439625

Inspection Document # 709400442

Adams, CO

NENE, 33 3S65W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Blue 3-65  
Location ID: 439625



**Photo 1.** Photo of location sign on site.



**Photo 2.** Photo of tank battery.



Inspection Photos  
Location Name: Blue 3-65  
Location ID: 439625



**Photo 3.** Photo of weeds on site.



**Photo 4.** Photo of weeds on site.