

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2023

Submitted Date:

08/01/2023

Document Number:

701007193

FIELD INSPECTION FORMLoc ID 304261 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	(970) 332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
254273	WELL	PR	11/01/2020	GW	125-08151	ALLEN 44-19	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Gravel road through pasture with cattle guard at entrance		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by fence		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by water tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Metal fence around unit, wellhead and metal shed		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor. Belts removed at time of inspection		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter run in metal shed		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator in metal shed		
Corrective Action:		Date:	

Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		39.690190,-102.219520	
Comment:	Fiberglass water tank 50% buried					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)	210bbbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	254273	Type:	WELL	API Number:	125-08151	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT