

TEP
W-43-28
Location ID:
335229



Well heads



Well heads

TEP
W-43-28
Location ID:
335229



Tank battery



Battery signage

TEP
W-43-28
Location ID:
335229



Separators



Lack of stabilization on cut slope and riling

TEP
W-43-28
Location ID:
335229



Run on



Lack of stabilization on cut slope

TEP
W-43-28
Location ID:
335229



Wattle is failing



Sediment trap is failing and under mined

TEP
W-43-28
Location ID:
335229



Sediment trap is failing and under mined



Sediment trap is failing and under mined

TEP
W-43-28
Location ID:
335229



Sediment migration off location



Sediment migration off location