

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Jensen/19-01 Pad

Location ID: 426451

Date: 8/2/2023



Southern Entrance to Location – Photo #05369



Wellhead – Photo #05372

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Jensen/19-01 Pad

Location ID: 426451

Date: 8/2/2023



Separator – Photo #05374



Tank Battery – Photo #05370

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Jensen/19-01 Pad

Location ID: 426451

Date: 8/2/2023



Location Lacks Stabilization – Photo #05371



Location Lacks Stabilization – Photo #05373

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Jensen/19-01 Pad

Location ID: 426451

Date: 8/2/2023



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #05375

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Jensen/19-01 Pad

Location ID: 426451

Date: 8/2/2023

– Photo #0

– Photo #0