

Inspection Photos

Location Name: MILLER DEPPE-65N64W/13SWNW

Location ID: 331160



Photo #1

Miller Deppe 12-13 (123-20245) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 160 yds.



Photo #2

Miller Deppe 11-13, 12-13, 22-13, #1 Battery site

Abandoned: ALL Equipment Removed



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources