

Inspection Photos

Location Name: MAGGIE-65N64W/13SWSW

Location ID: 330131



Photo #1

Maggie B 13-13 (123-18469) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 20 yds.



Photo #2

Maggie B 13-12, B 13-13 Battery site

Abandoned: ALL Equipment Removed



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources