

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Piceance/28-10 Pad

Location ID: 442549

Date: 8/3/2023



NW Entrance to Location – Photo #05447



NE Corner of Location – Photo #05448

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Piceance/28-10 Pad

Location ID: 442549

Date: 8/3/2023



SE Corner of Location – Photo #05449



SW Corner of Location – Photo #05450

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Piceance/28-10 Pad

Location ID: 442549

Date: 8/3/2023



Wellheads – Photo #05451



Separators – Photo #05452

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Piceance/28-10 Pad

Location ID: 442549

Date: 8/3/2023



Tank Battery – Photo #05454



Location Lacks Stabilization – Photo #05456

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Piceance/28-10 Pad

Location ID: 442549

Date: 8/3/2023



Location Lacks Stabilization – Photo #05457



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #05458