

Inspection Photos

Location Name: FORD-65N64W/13NESW

Location ID: 332053



Photo #1

Ford 23-13 (123-21771) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 200 yds.



Photo #2

Ford 23-13, 13-1 Battery site

Abandoned: ALL Equipment Removed



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources