

Inspection Photos
Location Name: Bledsoe 3-26-5-45
API Number: 125-09642



1. Well sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Bledsoe 3-26-5-45
API Number: 125-09642



3. Split in tubing joint just above well cap.



4. View of well site and damaged fencing.

Inspection Photos
Location Name: Bledsoe 3-26-5-45
API Number: 125-09642



5. Cement pad, production related debris inside fencing.



6. Well sign at remote meter shed.

Inspection Photos
Location Name: Bledsoe 3-26-5-45
API Number: 125-09642




7. Remote meter shed. Note vegetation.



8. Gas Meter inside remote Meter Shed.

Inspection Photos
Location Name: Bledsoe 3-26-5-45
API Number: 125-09642



9. View of Chart in Meter Box at time of inspection.

A photograph of a "Omimex Meter Test Report" form. The form contains the following information:

- Well Name: Bledsoe 3-26-5-45
- Date: 7-17-20
- Diff. Range: 0 to 100
- Static Range: 0 to 150
- Temp Average: 60
- Plate: 1250

The form also includes two tables for calibration data:

Differential		
Chart Read	Found	Left
0	0	0
100	100	100
50	50	50
0	0	0

Static		
Chart Read	Found	Left
0	0	0
150 (250)	150	150 (250)
75 (150) 125	75	75 (150) 125
0	0	0

The Inspector's signature is Logan. A timestamp "2023.08.02 11:18" is visible in the bottom right corner.

10. View of Mater Calibration/Test Log located inside Meter Shed at time of inspection.

Inspection Photos
Location Name: Bledsoe 3-26-5-45
API Number: 125-09642



11. Well location overview.



12. Remote Gas Meter Run overview.