

Inspection Photos

Operator: KINDER MORGAN CO2 CO LP – 46685

Location Name: MCELMO DOME UNIT 26-28-18 #YWD-1

Location ID: 313469 API #: 05-083-06195

Inspection Date: 8/3/2023 Inspection Doc#: 693806417



Location overview look N



Injection wellhead housing
Secondary containment of chemicals

Inspection Photos

Operator: KINDER MORGAN CO2 CO LP – 46685

Location Name: MCELMO DOME UNIT 26-28-18 #YWD-1

Location ID: 313469 API #: 05-083-06195

Inspection Date: 8/3/2023 Inspection Doc#: 693806417



Tank Battery



Manifold Housing and control station

Inspection Photos

Operator: KINDER MORGAN CO2 CO LP – 46685


Location Name: MCELMO DOME UNIT 26-28-18 #YWD-1

Location ID: 313469 API #: 05-083-06195

Inspection Date: 8/3/2023 Inspection Doc#: 693806417



Offload station



Sensor readout panel