

**Inspection Photos**  
**Location Name: Bledsoe 5-26-5-45**  
**API Number: 125-11952**



**1. Well sign at well location.**



**2. View of wellhead.**

**Inspection Photos**  
**Location Name: Bledsoe 5-26-5-45**  
**API Number: 125-11952**




**3. View of bubbles from gas leak at wellhead cap.**



**4. Well location overview.**



**Inspection Photos**  
**Location Name: Bledsoe 5-26-5-45**  
**API Number: 125-11952**




**5. Well sign with wrong API Number at remote meter shed.**



**6. View of Gas Meter inside Meter Shed.**

**Inspection Photos**  
**Location Name: Bledsoe 5-26-5-45**  
**API Number: 125-11952**



**7. View of Chart inside Meter Box at time of inspection.**

Omimex Meter Test Report

Well Name Bledsoe 5-26-5-45 Date 7-17-20

Diff. Range 0 to 100  
 Static Range 0 to 100  
 Temp Average 60

Plate 500

Differential			Static		
Chart Read	Found	Left	Chart Read	Found	Left
0	0	0	0	0	0
100	100	100	150 (260)	150	260 (250)
50	50	50	75 (±50) (125)	75	75 (±50) (125)
0	0	0	0	0	0

Inspector [Signature]

2023.08.02 11:46

**8. View of Meter Calibration/Test Log located inside Meter Shed.**



**Inspection Photos**  
**Location Name: Bledsoe 5-26-5-45**  
**API Number: 125-11952**



**9. View of Produced Water Tank at remote Gas Meter Run site. Note vegetation growth.**



**10. Overview of remote Gas Meter And Production Tank. Note vegetation growth.**