

Inspection Photos

Location Name: LOHR-65N64W/13NWNE

Location ID: 305928



Photo #1

Lohr #5 (123-23691) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 35 yds.



Photo #2

Lohr 32-13 Battery site

Inactive | Shut-down

Formerly served:

Lohr #5, 13-2, 13-4, 41-13 ;

Plugged & Abandoned | PA

Equipment Documented; Loc ID: 332065



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources