

Inspection Photos  
Location Name: Dreiling 27N, 27C-32 HZ  
Location ID: 434988



Photo 1: Pumpjacks



Photo 2: Tank Battery Signs

Inspection Photos  
Location Name: Drilling 27N, 27C-32 HZ  
Location ID: 434988



Photo 3: Tank Battery

Photo 4: Equipment

Inspection Photos  
Location Name: Dreiling 27N, 27C-32 HZ  
Location ID: 434988



Energy & Carbon Management Commission  
40.09074, -104.67854, 1480.8m, 337°  
Aug 2, 2023 11:21:28



Energy & Carbon Management Commission  
40.09072, -104.6786, 1485.4m, 326°  
Aug 2, 2023 11:21:48

Photo 5: Unused equipment

Photo 6: Unused equipment