

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Antelope P-29 Pad

Loc ID: 428984

Inspection: 696305126



Exhibit A



Exhibit B

CA: Unused Valves Pipes at North Set of Wells; see photos. Comply with Rule 606.

CA Resolution: Field has appropriately addressed and removed unused valve pipes at the North wells to comply with Rule 606.